

**SECRET**

64672

S E C R E T 271442Z MAR 68 CITE [ ] 3325

25X1

25X1

SUBJ GLASS LAMP

1. NORMAL PROCEDURE FOR REPORTING MAJOR MALFUNCTIONS REQUIRING IMMEDIATE ATTENTION IS TO CONTACT THE SAC REPRESENTATIVE (SG1 [ ] DET NO 1, 5544 ARTW) AT BOLLING AFB, WHO RELAYS THE INFORMATION TO THE FIELD UNIT. THE NORMAL CABLE EVALUATION IS THEN GENERATED. DURING 1968 ONLY ON ONE OCCASION, MISSION G -018, WAS IT FOUND NECESSARY TO CONTACT [ ]

25X1

25X1

2. CAMERA NO 18 CONSISTENTLY PROVIDES BETTER OVERALL IMAGE QUALITY THAN CAMERA NO 24 AS INDICATED BY THE EVALUATION CABLES. ALTHOUGH THE QUALITY PRODUCED BY CAMERA 24 DOES NOT PRESENT A MAJOR REPORTING PROBLEM AT THIS TIME; IT IS FELT THAT CORRECTIVE MEASURES COULD BE TAKEN TO IMPROVE THE IMAGERY BEING ACHIEVED BY THIS CAMERA. ONE SUGGESTED AREA TO BE INVESTIGATED WOULD BE THE ALIGNMENT OF THE LENS AND/OR MIRROR.

3. [ ] WOULD WELCOME THE OPPORTUNITY TO REVIEW THE GL EVALUATIONS WITH APPROPRIATE [ ] REPRESENTATIVE(S) AT THE [ ] FACILITY TO RESOLVE CURRENT PROBLEMS.

25X1

25X1

S E C R E T

END OF MSG

**SECRET**

DISTRIBUTION 7		
Cy No.	Office	Action
1	File	
	Cable Sec.	
	PP&B	
	Security	
345	TSSG	
	POG	
	IEG	
	IAS	
	DIAXX-4	
	SPAD	
	[ ]	

1968 MAR 27 15 57Z

25X1

Advance Copy  
Sanitized  
With Text

Declassification Review by NGA

GROUP 1  
Excluded from automatic  
downgrading and  
declassification